





Axle Bill Of Materials

97050 Series 300x90

80203 Rev A August 2015




Bill of Materials

97050

300x90 Brake Agri Axle

- **Brake Assembly (Page 1)**
- **Hub Assembly (Page 2)**
- **Camshaft and Lever (Page 3)**







granning

axle and suspension solutions


Brake Assembly




BRAKE ASSEMBLY– BILL OF MATERIALS			
Item	Part No	Description	Qty.
1	97555	Brake Shoe with Lining	4
2	97507	Brake Return Spring	4
3	97616	Anchor Pin	2
4	97598	Castle Nut	2
5	97546	Cotter Pin	2
6	97502	Camshaft Washer	4
7	97503	Camshaft Circlip	2
8	97625	Camshaft Bush (Cam Support)	2
9	97536	Seal (o-ring)	4
10	97624	Camshaft Bush (Anchor Bracket)	2



Hub Assembly



HUB ASSEMBLY– BILL OF MATERIALS			
Item	Part No.	Description	Qty.
1	97617	Hub Cap	2
2	97506	Castle Nut	2
3	97505	Cotter Pin	2
4	97614	Outer Bearing	2
5a	68154	Wheel Nut (DIN)	16
5b	68152	Wheel Inner Cone	16
5c	68153	Wheel Outer Cone	16
6	97622	Hub	2
7	97621	Drum	2
8	97615	Inner Bearing	2
9	97620	Grease Seal	2
10	97567	Wheel Bolt	16







granning

axle and suspension solutions


Camshaft Options



Item	Part No.	Description	Quantity
1	97652	507mm L/Hand	1
2		507mm R/Hand	1

Lever / Slack Options

Item	Description	Part No.	Dim. A	Dim. B	Dim. C	Dim. D	Dim. E
1	2 Hole Lever	20094	180mm	150mm	-	-	-
2	2 Hole Lever	97593	210mm	180mm	-	-	-
3	5 Hole Lever	97605	200mm	175mm	150mm	125mm	100mm
4	3 Hole Slack	20095	210mm	180mm	152mm	-	-
5	5 Hole Slack	97606	200mm	175mm	150mm	125mm	100mm





Our Offices

Ireland

Tel +353 (0) 45 897 553

Fax +353 (0) 45 848 638

UK

Tel +44 (0) 1925 817 689

Fax +44 (0) 1925 817 153

NI

Tel +44 (0) 2890 740 055

Fax +44 (0) 2890 752 718

Poland

Tel +48 (0) 29 753 1616

Fax +48 (0) 29 753 1604

sales@granningaxles.ie